

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant Report Date: 6/15/2012

1st Stage Feed

Sample Number: 122487-001 Date Collected: 06/06/2012 08:00 Date Received: 6/6/2012

ParameterResult UnitsData Qual PLMDL Analysis ByAnalysis Date/TimeMethodSelenium, Se394 ug/L0.50.1DPC06/11/2012 12:32EPA 200.8

2nd Stage Feed

Sample Number: 122487-002 Date Collected: 06/06/2012 08:00 Date Received: 6/6/2012

Parameter	Result Units	Data Qual	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	6.9 ug/L		0.5	0.1	DPC	06/11/2012 12:37	EPA 200.8

Bioreactor Effluent

Sample Number: 122487-003 Date Collected: 06/06/2012 08:00 Date Received: 6/6/2012

Parameter	Result Units	Data Qual	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	0.9 ug/L		0.5	0.1	DPC	06/11/2012 12:42	EPA 200.8

U: Analyte was analyzed and not detected at or above adjusted Method Detection Limit

Trisha Tucker, Chemist III

Email tltucker@aep.com Tel. 614-836-4184
Fax 614-836-4168 Audinet 210-4184

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.

J: Analyte was positively identified, though the quantitation was below Reporting Limit.